

## Photoelectric Label Sensor LAP Series

### Operation manual



[www.lanbaosensor.com](http://www.lanbaosensor.com)

### Precautions

- Please make sure that the power supply voltage is within the rated voltage range before powering on
- The sensor can be detected normally after 100ms of power charged on
- When using different power sources for the sensor and load, be sure to turn on the power of the sensor first
- When the sensor is not used, it is recommended to cut off the power of the load first and then turn off the power of the sensor
- Do not subject the sensor to severe external forces (such as hammer hits, etc.) during installation, so as not to damage the sensor performance
- Avoid using thinner, alcohol or other organic solvents when cleaning

### Safety Warning

- Do not use in an environment with flammable, explosive or corrosive gases
- Do not use in oil or chemical environments
- Do not use in a high humidity environment
- Do not use in direct sunlight
- Do not use in other environmental conditions that exceed the rated value
- Do not disassemble, repair or modify this product without authorization

### Scrap Treatment

- When the product is scrapped, please dispose of it as industrial waste

LAP-Ver.2.0 Z0218

This specification doesn't relate to patent responsibility. Moreover, our company is always devoting to improving product quality, and reserves the right to improve products by changing pattern or size without prior notice. We have considered all the notes when compiling this specification, but for the wrong or clipped parts, and any loss caused by using this manual information, we bear no responsibility.

Shanghai Lanbao Sensing Technology Co.,Ltd.

Address: No 228, Jinhui Road, Jinhui Industrial Park, Fengxian Area, Shanghai, China  
Zip code: 201404

TEL: 021-57486188 57486189 FAX: 86-021-57486199


Email: market@shlanbao.cn Hotline: 800-820-8259

### ■ Technical specifications



Model	NPN	LAP-TR03TNB	LAP-TR03TNB-F3
	PNP	LAP-TR03TPB	LAP-TR03TPB-F3
Slot width	3mm		
Slot depth	60mm		
Label minimum spacing	≥2mm		
Light source	Infrared light(940nm)		
Response frequency	Max 10kHz		
Label passing speed	≤20m/min (0.3m/s)		
Response time	≤50μs		
Delay after startup	≤300ms		
Supply voltage high/low	12...24VDC(Ripple≤15%)		
Current consumption	≤30mA		
Warning output	Red indicator light on		
Switch output function	Light on/ dark on (Switchable)		
Voltage drop	≤2.5V		
Output current	≤50mA		
Indicator	Red light: Calibration error / operation error; Green light: NO NC; Blue light: detect label switch output signal		
Operation temperature	-20...60°C(No icing, no condensation)		
Storage temperature	-30...70°C		
Protection degree	IP65		
VDE safety level	III		
Weight	Approximately 55g (100g with wire)		
Material	Zinc die casting; surface electroless nickel plating (Silver); PC plastic		
Connection	2m 3 pins cable	25cm cable+ M8 connector	

### ■ Wiring diagram


NPN



PNP



### ■ Dimensions



### 4.3 Dynamic indication

- Push a label conveyor with a maximum speed of 20m/min and pass through the sensor, with at least 3 to 7 labels passing through the sensor.
- Press the calibration button briefly to end the calibration operation, and the sensor enters standard mode.

### 4.4 Static teaching

- Blank area is maintained in the detection area of the sensor.
- Press the calibration button briefly to end the calibration operation, and the sensor enters standard mode.
- If the calibration operation is wrong (e.g., the detected label is transparent or uneven), the red light will turn on, the green light and the blue light will flash quickly, and the error output signal will also be generated.
- When an error occurs, the operation must be re-calibrated. After re-calibration, if the error cannot be corrected, then this type of labels does not apply to the product.

### Operation process:

The calibration button must be pressed for at least 3 seconds to operate the product.

Basic operation in standard mode

Error indicator-Red light  
NO/NC indicator-Green light  
Switch signal output indicator-Blue light

Press ≥12s           Return

Calibration “NO and NC mode”

Set switch output: Output switch signal in gap/tag  
Green light is always on. Press the SET key again to normally use the current instruction for signal output and switch off behavior  
(The blue output indicator lights up normally and the ON/OFF signal output switches normally), then the setting is terminated.

Blue light: on= signal output in gap; off= signal output in label

[NC settings] Press and hold SET key for 12 seconds, the green and blue lights flash simultaneously. After 12 seconds, the green light off .Press the button again to normally use the current instruction for signal output and off switching behavior  
(The blue output indicator lights up normally and the ON/OFF signal output switches normally), then the setting is terminated.

Blue light: on= signal output in label; off= signal output in gap

≥3s           Press Return

Calibration of “Setting object”(Take NO as an example )

For non-transparent label detection (Static or mobile operation)  
[NO settings] Press the SET key for 12 seconds and the green and blue lights flash simultaneously. After 12 seconds, place the gap or blank area of the label to be detected under the detection area, press the SET key for 3 seconds, and the green and blue lights flash simultaneously.

Place the label to be tested under the inspection area, press the SET key to stop the calibration, the blue light is off and the green light is always on.Freely switch between the label and the gap in the sensor, the blue output indicator lights up normally, then set correctly.

Error indicator - Red light: If there is no error in the calibration, the red light is off.

\*Normal closed mode, detection is the opposite of normal open mode.

### 4.5 Calibration teaching

The label sensor has the sensitivity to correctly detect various labels at high speed.

#### 4.1 Dynamic calibration preparation

- Insert the label conveyor into the sensor.

#### 4.2 Static calibration preparation

- Move the label out of the sensor substrate and push the blank area into the sensor.
- Press and hold the calibration button for 3 seconds until both the green and blue lights flash simultaneously.
- Release the calibration button.